


Flat Rate Repair Pricing

Questions, Call 801.546-4146 or 1.800.498.5795

Best Service, Best Price

BEST WARRANTY -- All repairs have a 6 month warranty

No extra charge for bench time or non-repairables

Product	Internal Item #	Item	Description	Price
 Dispensers	REP-00045	TDM50	Refurbish Triton TDM50 Dispenser *	\$ 329.00
	REP-00001	TDM100	Refurbish Triton TDM100 Dispenser *	\$ 229.00
	REP-00002	TDM150	Refurbish Triton TDM150 Dispenser *	\$ 249.00
	REP-00003	TDM200	Refurbish Triton TDM200 Dispenser *	\$ 349.00
	REP-00004	TDM250	Refurbish Triton TDM250 Dispenser *	\$ 379.00
	REP-00005	Dispenser Board Repair	Repair Triton Dispenser Board, if needed	\$ 100.00
		De La Rue (see De La Rue section below)		
		Uninote for MAKO (see Uninote section below)		
Cassettes	REP-00006	TDM100 Cassette	Refurbish Triton TDM100 Cassette **	\$ 75.00
	REP-00007	TDM150 Cassette	Refurbish Triton TDM150 Cassette **	\$ 75.00
	REP-00024	Bill Pick Assy	Replace Bill Pick Assembly, if needed	\$ 100.00
Keypad	REP-00037	All	Repair Keypad	\$ 75.00
Electronics	REP-00008	9100	Refurbish Triton 9100 Mainboard	\$ 169.00
	REP-00009	9700	Refurbish Triton 9700 Mainboard	\$ 169.00
	REP-00010	9600	Refurbish Triton 9600 Mainboard	\$ 169.00
	REP-00011	RL5000	Refurbish Triton RL5000 Mainboard	\$ 299.00
	REP-00052	RL/FT5000, RL2000	Refurbish Docking Board	\$ 145.00
Printers	REP-00047	9600 Printer	Refurbish 9600 Printer Assembly	\$ 249.00
	REP-00048	9100/9700/8100 Printer	Refurbish 9100/9700 or 8100 Printer Assembly	\$ 199.00
	REP-00053	RL2000/RL5000	Refurbish Printer Presenter Assembly	\$ 79.00
LCDs	REP-00012	LCD (screen)	Refurbish Triton 5.7" LCD	\$ 79.00
	REP-00046	LCD (Screen)	Refurbish Triton 10.4" Color LCD	\$ 349.00
Power Supplies	REP-00013	Power Supply	Refurbish Triton Power Supply	\$ 159.00



Dispensers	REP-00029	SDD	Refurbish De La Rue SDD Dispenser. Includes Metal Rails and Metal Timing Wheel Cover.*	\$ 249.00
	REP-00030	Mini Mech	Refurbish De La Rue Mini Mech Dispenser*	\$ 179.00
	REP-00031	NMD50	Refurbish De La Rue NMD100 Dispenser (two High)*	\$ 399.00
	REP-00032	NMD100	Refurbish De La Rue NMD100 Dispenser*	\$ 499.00
	REP-00033	Dispenser Board Repair	Repair De La Rue Dispenser Board, if needed	\$ 100.00
Cassettes	REP-00034	SDD Cassette	Refurbish De La Rue SDD Cassette. Includes Metal Rails	\$ 149.00
	REP-00035	NMD50 Cassette	Refurbish De La Rue NMD50 Cassette	\$ 149.00
	REP-00036	NMD100 Cassette	Refurbish De La Rue NMD100 Cassette	\$ 149.00



and



REP-00042	Fujitsu (used in Tidel IS2000 ATM)	Refurbish Fujitsu Dispenser*	\$ 349.00
REP-00043	Fujitsu Cassette	Refurbish Fujitsu Cassette	\$ 149.00

Dispensers

REP-00014	1,000 Note	Refurbish Hyosung 1,000 Note Dispenser *	\$ 249.00
REP-00015	2,000 Note	Refurbish Hyosung 2,000 Note Dispenser *	\$ 299.00
REP-00040	4,000 Note	Refurbish Hyosung 4,000 Note Dispenser *	\$ 349.00
REP-00041	6-8,000 Note	Refurbish Hyosung 6-8,000 Note Dispenser *	\$ 449.00
REP-00016	Drawer Style	Refurbish Hyosung Drawer Style Dispenser. Price includes repairing/replacing bill pick assembly if needed. *	\$ 349.00
REP-00017	TCDU (800 Note Fixed)	Refurbish Tranax TCDU Dispenser *	\$ 249.00
REP-00018	MCDU Single	Refurbish Tranax MCDU Single Cassette Dispenser *	\$ 299.00
REP-00019	MCDU Multiple	Refurbish Tranax MCDU Multiple Cassette Dispenser *	\$ 399.00
REP-00020	Dispenser Board Repair	Repair Hyosung/Tranax Dispenser Board, if needed	\$ 100.00

Cassettes

REP-00021	1,000 Note Cassette	Refurbish Hyosung 1,000 Note Cassette. Price includes replacing bill pick assembly if needed.	\$ 149.00
REP-00022	2,000 Note Cassette	Refurbish Hyosung 2,000 Note Cassette. Price includes replacing bill pick assembly if needed.	\$ 149.00
REP-00049	Note Separator	Refurbish Hyosung Note Separator Assembly	\$ 149.00
REP-00023	MCDU Cassette	Refurbish Tranax MCDU Cassette	\$ 149.00

Keypad

REP-00050	All	Repair Hyosung or Tranax Keypad	\$ 179.00
-----------	------------	---------------------------------	-----------

Mainboards

REP-00025	Mainboard	Refurbish Hyosung/Tranax Mainboard	\$ 75.00
REP-00026	Mainboard Extensive	Refurbish Hyosung/Tranax Mainboard requiring Extensive Component Repair	\$ 145.00

Printers

REP-00038	All Printers	Refurbish Hyosung Printer (Printer board repair not included)	\$ 249.00
REP-00039	Printer Board Repair	Repair Hyosung Printer Board, if needed	\$ 100.00

LCDs

REP-00027	LCD (Screen)	Refurbish Hyosung/Tranax LCD	\$ 149.00
-----------	---------------------	------------------------------	-----------

Power Supplies

REP-00028	Power Supply	Refurbish Hyosung/Tranax Power Supply	\$ 169.00
-----------	---------------------	---------------------------------------	-----------

UNINOTE (for MAKO)

REP-00044	Uninote Dispenser (used in Triton MAKO).	Refurbish Uninote Dispenser*	\$ 349.00
-----------	---	------------------------------	-----------

* Price does not include dispenser board repair if needed. Add \$100 if dispenser Board requires component repair. Add \$100 for Rodent Damage.

Shipping Address for Repair Items:

ATMEquipment.com
 ATTN: Repair Dept.
 854 West 450 North, Suite 4
 Kaysville, UT 84037